Title: H1 HIGH TENSION WIRING



©Kawasaki Motors Corp 1974 Printed in USA

PROBLEM:

An early H1 may start losing power, misfiring, backfiring, or stop running altogether. Installation of new spark plugs seems to clear up the problem, leaving the impression that the used plugs were defective. However, the problem returns after a short period of use with the new spark plugs.


CAUSE:

The spark plugs generally are not the cause of the problem. We have found the high tension wiring leaks electricity to adjoining metal engine parts under high voltage loads. New spark plugs require less voltage to fire because the electrodes have sharp edges. As the plugs are used, these sharp edges are rounded off by high energy discharge and erosion from heat and chemical action in the combustion chamber. Consequently, they require an increasing amount of voltage to fire as mileage accumulates. Worn spark plugs, over-rich oil pump settings, or incorrect fuel mixtures demand more voltage from the ignition system to fire the spark plugs. These conditions "back up" the voltage in the secondary wiring until it jumps through the H.T. cord insulation to an inviting engine ground rather than fire the plugs.

CORRECTION:

KAWASAKI has developed a set of high tension components which, after thorough testing, has proven completely reliable and eliminates the insulation leakage problem. The purpose of the new components is to re-route the H.T. cords so they are a safe distance from metal engine grounds like the oil pump, oil pump cover, engine cover, cylinders, carburetors, etc. Additionally, the type of H.T. cord has been changed from DAIICHI brand to Belden, a better-insulated cable.


EARLY H.T. WIRING



H1 with original H.T. wiring



LATE H.T. WIRING



H1 with new H.T. wiring kit (P/N 99990-015)




APPLICATION:

The new H.T. components were incorporated on H1's after Engine KAE-08800. The drain grommet was not used until KAE-11300, so on units from KAE-08800 to KAE-11300, the oil pump cover is not notched for the drain grommet.

PARTS ORDERING:

If you want to convert an older H1 to all new parts, the component parts are available separately.




PARTS INFORMATION:

| DESCRIPTION | OLD PARTS | | NEW PARTS | | INTER- CHANGE | EFFECTIVE |
|-------------------------|-----------|---------------------|-----------|---------------------------------|---------------------------|-----------|
| | OLD P/N | REMARKS | NEW P/N | REMARKS | OLD-NEW | I.D. |
| Oil Pump Cover | 14030-013 | | 14030-025 | w/notch for drain grommet | - X → | KAE-11300 |
| H.T. Cord Grommet | 92071-040 | | 92071-043 | | ▼ 0 ONLY AS | KAE-08800 |
| Oil Pump Lever Cover | 14030-014 | Aluminum | 14030-024 | Plastic | A SET | |
| H.T. Cord Protector | 92115-001 | 145mm | 92115-002 | 120mm | | |
| Dist. Cap Grommet | 92071-031 | 2 Per Motorcycle | Same | 2 per motorcycle | | |
| Drain Grom- met | | | 16116-005 | New Part | → X | KAE-11300 |
| H.T. Cord Assy. | 21150-001 | | 21150-003 | Belden wire | - X → | KAE-08800 |

O = interchangeable $X = not interchangeable \Box = not available$

NOTE: Watch the following items when installing the new parts.



To save time, use the photo above for inserting the cords in the grommet. The bottom cords should protrude 1" more than the top ones.

Use Rubber band P/N 92072-013 to fix loom to right frame tube under gas tank.



To keep water from entering, make sure the bottom of the grommet is hooked onto the crankcase. Route the H.T. cords over the RH carburetor, NOT between the carburetor and cylinder.

Jam the H.T. cords completely into the distributor cap sockets before installing the piercing screws.

REPLACING H.T. CORDS:

The only high tension wire assembly available in stock for the early H1 is the BELDEN #7789 secondary wire (P/N 21150-003). This cable is also stocked by most auto parts jobbers in 100 ft. reels. The H.T. cord lengths are listed below.

| CORD USE | LENGTH | | |
|--------------------|----------------|--|--|
| Center Cylinder | 24.8" (63cm) | | |
| Right Cylinder | 27.5" (70cm) | | |
| Ignition Coil | 22.5" (57cm) | | |
| Left Cylinder | 26.3" (67cm) | | |
| Total Length Req'd | 101.1" (257cm) | | |

WARRANTY INFORMATION:

Use job code X006 (0.7 hr.) for updating the high tension assy. on any H1 before engine number KAE-08800. This is a factory directed modification, CLAIM TYPE 3 on the Warranty Request Form.

NOTE: Dealers subscribing to the Small Claims Option Program are required to perform this modification and submit a Warranty Request Form for each unit so modified. The Small Claims Option Program applies to claim types 1 and 2 only. ■