

©Kawasaki Motors Corp 1974 Printed in USA

*obsolete*

## PROBLEM:

There have been complaints on early H1B motorcycles of sluggish performance in the low and middle rpm range.


## SOLUTION:

To improve the overall performance of the H1B, a new air cleaner was designed and a new set of carburetor specifications was used from mid-1972 production. This change is applied to all H1B's from engine number KAE-61607 and up.




The new air cleaner has two additional air intake ducts to increase the air intake capacity.

## NEW CARBURETOR SPECIFICATIONS:

	OLD	NEW
Type	VM28SC	VM28SC
I.D. Mark	KA2	KA5
Main Jet	100	95
Needle Jet	0-4	0-4/8mm
Jet Needle	5DJ19-3	5DJ19-4
T. V. Cutaway	2.5	2.0
Pilot Jet	30	30
Air Screw (turns)	1-1/4	1-1/2



## PARTS INFORMATION:

DESCRIPTION	OLD PART		NEW PART		INTER-CHANGE	EFFECTIVE I.D.
	OLD P/N	REMARKS	NEW P/N	REMARKS	OLD↔NEW	
Carburetor Assy L.H. & C.	16001-143		16001-151		 as a set	KAE-61607
Carburetor Assy R.H.	16001-144		16001-152			
Air Cleaner	11010-035-10		11010-058-21	2 Addl. Air Ducts		
Main Jet	92063-070	#100	92063-069	#95	 only as a set	
Needle Jet	16017-058	0-4	16017-062	0-4/8mm		
Throttle Valve	16025-046	2.5	16025-048	2.0		

O = interchangeable    X = not interchangeable    □ = not available

## WARRANTY INFORMATION:

This was a factory production change for routine product improvement. This bulletin is for notification of modification only, not for warranty authorization. ■